

Removing Floor Finishes and Sealers

1. Wet floor. Allow to stand 10 minutes. Do not allow solution to dry on floor.
2. Machine scrub.
3. Pick up solution.
4. Rinse floor at least twice with cold water.
5. After floor is dry, apply floor finish.